

ATTACHMENT 5 Color Photographs



Pre Storm Aerial Photo from Google Earth



This picture is from the minutes of the October 30, 2009, meeting involving the applicant and representatives of the Department, Maine Geological Survey, and U.S. Army Corps of Engineers. The picture shows the breach in the vertical bulkhead at Mrs. Stone's property. The beach club can be seen in the background. The corner of Mrs. Stone's residence can be seen on the right side of the photo.



April 07 storm damage. Looking across Stone property towards the Prouts Neck Beach Club.




Pre-storm damage condition of Stone property above. Note 'bump' in horizontal wall alignment. Contrast with April 2007 damage below. Note that the Prouts Neck Beach Club wall was replaced in 2006.





Close up of April 2007 storm damage.





Replacement of Dune Grass on Rockefeller Property. Kohlberg property beyond.